

25X1A

BLACKSHIELD

	TITLE	DUE		IN	OUT	ACTION	REMARKS
		LCL	Z				
✓							
✓	Msn Alert Wx Fcst	-25 0630		X		WX	(Receive Daily)
✓	Airfield Status	Daily 0900			X	DCOC (Controll)	As of 0900L Filed in <input type="checkbox"/> Folder
✓	Tanker Msn Alert	-24 0730		X		SAC	25X1A
✓	Mission Alert	-24 0730		X		CMDR/DCO DCM	
25X1A ✓	Ackd Receipt <input type="checkbox"/>	ASAP ASAP			X	DCOC	
✓	Mission Plan Wx Requirement	-23 0830		X		WX/DCO	
✓	Opln Commo Data	-22 0930		X		COMMO/DCO	
25X1 ✓	<input type="checkbox"/> Setting	-22 0930		X		<input type="checkbox"/>	25X1
✓	Tanker/Wx Scout Recall Word	-22 0930		X		SAC/DCO	
✓	Mission Alert Confirmation	-21 0930			X	DCO	
✓	Tanker Support Confirmation	-21 0930			X	SAC	
✓	Msn Plan Wx Fcst	-21 1030		X		WX	
✓	Forward Base Wx Forecast	-21 1030		X		WX	25X1A
✓	<input type="checkbox"/>	-20 1030			X	DCO	<input type="checkbox"/>

PAGE 1

REVISED 5 SEP 67

25X1A

25X1D

BLACKSHIELD

	TITLE	DUE		IN	OUT	ACTION	REMARKS
		LCL	Z				
✓	HF Freg to TTFC	-20 1030			X	COMMO	
✓	MISSION PLAN#1	-18 1330		X		DCOMP	
✓	Current Intel	-18 1330		X		INTEL	
✓	Msn Pln Wx Fcst	-17:30 1400		X		WX	
✓	Wx Support Confirmation	-17:30 1400		X		DCOC	25X1A
✓	Weather Scout Call Sign Confirmation	-17:00 1330			X	DCO	Wx Scout Call Signs to <input type="text"/> WECEN
✓	Forward Base Wx Forecast	-17:15 1415		X		WX	
✓	Opln Capability	-16:00 1430			X	DCM	As of 1700 Local Daily
✓	Supt Acft Statu	-15:00 1530			X	DCM	As of 1700 Local Daily
✓	Mission Pln#2	-15:00 1630		X		DCOMP	Probably 1004 RCCD
✓	Mission Plan#3	-15:00 1630		X		DCOMP	Probably 1004
25X1A	<input type="checkbox"/> Sys Checkout	-15:00 1530			X	DCM	REQUIRED ONLY WHEN SO INDICATED ON BOTTOM OF <input type="text"/> 25X1A
NR	GO-NO-GO Wx Requirements	NLT 1330Z 2130		X		Wx	
✓	nkrr Msn Wx Fcst	-1730		X		SAC/WX	

25X1A

BLACKSHIELD

	✓	TITLE	DUE		IN	OUT	ACTION	REMARKS
			LCL	Z				
25X1	✓	Tanker Msn Plan	-13:00		X		SAC	Probably More Than 1 Msg
	✓	Camera Program- ing Data	-12:30		X		DCOMP	Probably 1004
25X1A	✓	Support Request	-12:00			X	DCO	Add Crew Number
25X1A	✓		-10:00			X	COMMO	
	✓	Non-Opnl Sortie	DAILY			X	DCOC (CONTROL)	File in Folder Sub- mitted Appox 1530L Daily For Next Days Non-Ops Msn
	✓	Sp Fuel Test	-10:00			X	DCM(POL)	
		Forward Base Wx Forecast	-9:00			X	WX	
	✓	Tanker Pre- Sortie Report	-9:00			X	SAC	Probably More Than 1 Msg
25X1		GO-NO-GO WX Forecast	-9:00		X		WX	
	✓	Pre-Sortie Report	-9:00			X	DCO	
		Haz Wx Advisory	-7:00			X	WX	If Adverse Conditions
		Haz Wx Advisory	-7:00		X		WX	If Adverse Conditions
		Tanker Msn Support Execut- ion	-6:00		X		SAC	
25X1	✓	Approved For Release 2002/10/31 : CIA-RDP69B00041R00260090014-7				X	DCOM	

25X1A

BLACKSHIELD

	TITLE	DUE		IN	OUT	ACTION	REMARKS
		LCL	Z				
25X1	Final Option Selection	-6 0130		X		DCOM	
	Msn Alert Wx Fcst	-5 0230		X		WX	(Receive Daily)
	Emerg Seat Pack	-5 030			X	SECURITY	
	Forward Base Wx Forecast	-3 0330			X	WX	
	Met Watch Obs	-3 0330			X	WX	
25X1A		-3 0430		X		DCO	
	GO-NO-GO Wx Forecast	-3 0430		X		WX	
	Spl Fuel Test	-2:30 0400			X	DCM(POL)	
	313 AD Coord Confirmation	-2:30 0400			X	DCO	Submit to Hqs
25X1	Wx Scout Rpts	-2 0530		X		WX	Will be Received Continuous Until AR Areas Secured
	Airfield Status	Daily ASAP			X	DCOC (Controll)	As of 0900 Local Filed in <input type="text"/> Folder
	Tanker T/O Rpt	As Req			X	SAC	25X1A Continous Until all Tankers are Airborne
	GO-NO-GO Msgs	-1 0630		X		DCO	
	Primary Take-off	-0 0730			X	DCO	Add Crew Number

25X1A

BLACKSHIELD

✓	TITLE	EJE		IN	OUT	ACTION	REMARKS
		LCL	Z				
25X1	Primary Take-off	-0			X	DCO	25X1A
		6730					
	Primary Abort	As Req			X	DCO	FLASH 25X1A
	Primary Abort	As Req			X	DCO	
	Spare Take-off	As Req			X	DCO	Add Crew Number
	Spare Take-off	As Req			X	DCO	25X1A
25X1	Tanker Off-load Rpt	As Req		X		DCO/SAC	Continuous Until All Fuel Off Loaded
	Primary Landing	L			X	DCO	
	Primary Landing (Canx 313 Support If Msn Completed)	L			X	DCO	25X1A
	Spare Abort	As Req			X	DCO	FLASH
	Spare Abort (Canx 313 Support If Msn Cancelled)	As Req			X	DCO	
25X1	Spare Landing	L			X	DCO	25X1A
	Spare Landing (Canx 313 Support)	L			X	DCO	
	<input type="checkbox"/> Resume	ASAP			X	COMMO	
	Support Termination	ASAP		X		SAC/WX	

25X1A

BLACKSHIELD

✓	TITLE	DUE		IN	OUT	ACTION	REMARKS
		LCL	Z				
	Msn Post Landing	L Plus 2			X	DCO/CMDR	
	Tanker Landing	As Req			X	SAC	Continuous: Until all Tankers Have Landed
	Camera Config	L Plus 3			X	DCM	
	Mission Report	L Plus 3			X	DCO/DCOM	25X1A INFO: <input type="checkbox"/> "EYES ONLY CMDR"
	Spl Fuel Test	ASAP			X	DCM(POL)	
	Opnl Sortie Rpt	ASAP			X	DCO	25X1A Same as Nonop <input type="checkbox"/>
	INS Tape	ASAP			X	DCOMP	Via 1004 w/message back-up
	Take Progress	ASAP			X	SECURITY	
	Final Field Eval Of INS Data	L Plus 10			X	DCM	
	Flash Process	ASAP		X		DCOMP	
	Film Evaluation	ASAP		X		DCOMP	
	INS Tape Eval	ASAP		X		DCOMP	
	INS Film Correle.	L Plus 7 Days		X		DCOMP	
	SYSTEMS VI TAKE PROGRESS RPT	ASAP			X	SECURITY	